

FIG. 1.




FIG. 2.




FIG. 9.




FIG. 3.




FIG. 4.




FIG. 5.




FIG. 6.




FIG. 7.




FIG. 8.

FIG. 10.

Thermal Stress & Strength Failure (Spline)  
Reference Temperature= -30 C  
Spline Fitted

